

**PROFORMA FOR THE SAFETY OF SCHOOL BUILDING
PART- 1**

(To be filled by the Head of School/ Institute)

1. Name of the School :- Maharishi Vidya Mandir
2. Location :- Bilona, Distt- Bageshwer (UK.)
3. Plot Area: - 93654.00Sqft.
4. Plinth Area: - 7831.00Sqft.
5. Number of Storey's :- G+2
6. Year of Construction of Building: - 2012

7. If the building has been constructed under the supervision of the qualified Engineer, the following details may be given
 - (a) Name of the Engineer with qualification: - Sh. B.P. Sharma (Diploma Civil)
 - (b) Address of Engineer: - E- Block, Maharishi Nagar Noida
 - (c) Set of Structural drawings used in the construction, if available: - Attached
 - (d) Name & address of Architect with qualification: - Harindra Baba (B Arch)
Rajori Garden New Delhi

8. Whether the building has been constructed for the purpose
 - (a) School :- Yes
 - (b) Residential Purpose and converted for use as a School: - No

9. Materials used for roofs
 - (a) R.C.C. Slabs/R.B.C. Slabs: - Yes
 - (b) R.S. Joist & Battons: - No
 - (c) Wooden joists & Battons:- No

10. Materials used for walls
 - (a) Mud Mortar:- No
 - (b) Cement Mortar:- Yes
 - (c) Lime Mortar:- No

11. Flooring
 - (a) Conglomerate:- No
 - (b) Terrazzo:- Yes
 - (c) Brick Paving:- No

12. A detailed drawing indicating dimensions of the rooms Along with size and location of doors and windows (Attached)


Principal
Maharishi Vidya Mandir
Bilona Bageshwar (UK)
Signature with Stamp of the seal
of the School/Institution.

PART-II
(To be filled by the S.D.E)

- a) I have visited the above mentioned school on dated ...17/06/2021.....And have visually inspected it from all angles of safety and find it fit for normal use as school building.
- b) In case any addition/alteration or extension and modification to the building is to be carried out, the same be carried out under the supervision of a qualified Engineer and this certificate may be reobtained after the completion from the undersigned.
- c) In case the building is affected by flood or if there is settlement of walls/foundation or sagging of roofs etc. immediate inspection of the undersigned by arranged to check the stability and safety of the building.
- d) This building can be safety occupied for normal use upto (indicate upto which it can be used) for about next 50 years.

B
17/06/2021
सहायक अभियन्ता
Sub Divisional Engineer
प्रांतीय अर्थ, लोनिवा
बागेश्वर